

Daily Progress Report


10-07-2025

Work Location: Summit to Summit Motorway (Los Angeles County)

APN: 2080-013-902; 4434-003-901

Overview:

The masticator continued to clear 20 feet of brush from both sides of the road along Summit to Summit Motorway. The masticator cleared a stretch of 1,423 feet along Summit to Summit Motorway.



Daily Progress Report


10-08-2025

Work Location: Summit to Summit Motorway (Los Angeles County)

APN: 2080-013-902; 4434-003-901

Overview:

The masticator continued to clear 20 feet of brush from both sides of the road along Summit to Summit Motorway. The masticator cleared a stretch of 1,600.9 feet along Summit to Summit Motorway.



Daily Progress Report


10-10-2025

Work Location: Summit to Summit Motorway (Los Angeles County)

APN: 2080-013-902; 4434-003-901

Overview:

The masticator continued to clear 20 feet of brush from both sides of the road along Summit to Summit Motorway. The masticator cleared a stretch of 4,179.7 feet along Summit to Summit Motorway. The masticator completed the clearance on Summit to Summit motorway tying into highway 27.



Daily Progress Report

10-07-2025 – 10-10-2025

Work Location: North Crummer (Ventura County)

APN: 685-0-070-090

Overview: The goats and sheep have cleared a total of 20 acres behind the community.



