

Daily Progress Report


10-21-2025

Work Location: Calabasas Peak Motorway (Los Angeles County)

APN: 4436-001-905

Overview:

The masticator continued to clear 20 feet of brush from both sides of the road along Calabasas Peak Motorway beginning at Old Topanga Canyon Rd. The masticator cleared a stretch of 643 feet along Calabasas Peak Motorway.



Daily Progress Report


10-23-2025

Work Location: Calabasas Peak Motorway (Los Angeles County)

APN: 4436-001-905

Overview:

The masticator continued to clear 20 feet of brush from both sides of the road along Calabasas Peak Motorway beginning at Old Topanga Canyon Rd. The masticator cleared a stretch of 851 feet along Calabasas Peak Motorway.



Daily Progress Report

10-18-2025 – 10-24-2025

Work Location: North Crummer (Ventura County)

APN: 685-0-070-090

Overview: The goats and sheep have cleared 8.20 acres this week focusing on improving clearance along the road. A total of 46.54 acres have been cleared by the goats.

